


Step 3

Remove the perforator shaft from the machine by moving the shaft to the left.

For the bottom perforator shaft repeat steps 1-3. Installation involves a reversal of steps 1-3.

Design of the perforators and cutters



A - Guide rollers
B - Tool holder, bottom (Allen screw LEFT)
C - Tool holder, top (Allen screw RIGHT)
D - Counterpressure spring
E - Wiper

I. - Perforator shaft, top
II. - Perforator shaft, bottom

Артикул	6734
Название	Направляющая для перфорации
Английское (немецкое) название	Wiper
Каталожный номер	PS6734
Производство	Швейцария
Цена	По запросу
Дата	19.06.2026