


### Step 3

Remove the perforator shaft from the machine by moving the shaft to the left.

For the bottom perforator shaft repeat steps 1-3. Installation involves a reversal of steps 1-3.

### Design of the perforators and cutters



A - Guide rollers  
B - Tool holder, bottom (Allen screw LEFT)  
C - Tool holder, top (Allen screw RIGHT)  
D - Counterpressure spring  
E - Wiper

I. - Perforator shaft, top  
II. - Perforator shaft, bottom

Артикул	6734
Название	<a href="#">Направляющая для перфорации</a>
Английское (немецкое) название	Wiper
Каталожный номер	PS6734
Производство	Швейцария
Цена	По запросу
Дата	29.04.2026